


# FAST

FAST FASTENING



## DYCKERT 1,2X25 BANDAD FZB PKT=5000

### Dykkert rettbåndet 1,2 elforsinket FAST

For innfesting av innvendig listverk, sokler, foringer, taklister m.m. 18 Gauge. Overflatebehandling: Elforsinket. Pakke.

### Kataloginfo

Artikelnr	Dimension D x L mm	Innehåll	Antal/fp
<a href="#">294053</a>	1,2x25	5000	20
<a href="#">294055</a>	1,2x35	5000	10
<a href="#">294057</a>	1,2x40	5000	10
<a href="#">294059</a>	1,2x45	5000	10
<a href="#">294061</a>	1,2x50	5000	10

### Verktøyguide

Verktøy	294053	294055	294057	294059	294061
<b>Basso</b>	B18/50S-A1S, B18/55-A1, B18/32P, B18/32-2, B18/35, B18/35P, B18/50	B18/50S-A1S, B18/55-A1, B18/32P, B18/32-2, B18/35, B18/35P, B18/50	B18/50S-A1S, B18/55-A1, B18/50, B18/50P-A3, B18/50P-B1	B18/50S-A1S, B18/55-A1, B18/50, B18/50P-A3, B18/50P-B1	B18/50S-A1S, B18/55-A1, B18/50, B18/50P-A3, B18/50P-B1
<b>BEA</b>	SE 355-221	SE 355-221	SE 355-221	SE 355-221	SE 355-221
<b>Biltema</b>	15-530	15-530	15-530	15-530	15-530
<b>Bosch</b>	GSK50, GTK40, HT14, PTK 14E, PEK 19E, PTK 23E	GSK50, GTK40, HT14, PTK 14E, PEK 19E, PTK 23E	GSK50, GTK40, HT14, PTK 14E, PEK 19E, PTK 23E	GSK50, GTK40, HT14, PTK 14E, PEK 19E, PTK 23E	GSK50, GTK40, HT14, PTK 14E, PEK 19E, PTK 23E
<b>Bostitch Stanley</b>	HD 14, ST 14, Vario 14, BT1855,	HD 14, ST 14, Vario 14, BT1855,	HD 14, ST 14, Vario 14, BT1855,	HD 14, ST 14, Vario 14, BT1855,	HD 14, ST 14, Vario 14, BT1855,

	GBT1850, SB1850, SB1855, BT 50	GBT1850, SB1850, SB1855, BT 50	GBT1850, SB1850, SB1855, BT 50	GBT1850, SB1850, SB1855, BT 50	GBT1850, SB1850, SB1855, BT 50
<b>Duofast</b>	FN4455	FN4455	FN4455	FN4455	FN4455
<b>Dewalt</b>	D51238K, DC602KB, DC608KB	D51238K, DC602KB, DC608KB	D51238K, DC602KB, DC608KB	D51238K, DC602KB, DC608KB	D51238K, DC602KB, DC608KB
<b>Gebe</b>	F50/9040, F50C	F50/9040, F50C	F50/9040, F50C	F50/9040, F50C	F50/9040, F50C
<b>Haubold</b>	ATT 420 SC, Combi AMT- 6232, SKN 30 JN-12	ATT 420 SC, Combi AMT- 6232, SKN 30 JN-12	ATT 420 SC, Combi AMT-6232, SKN 30 JN- 12	ATT 420 SC, Combi AMT-6232, SKN 30 JN- 12	ATT 420 SC, Combi AMT- 6232, SKN 30 JN-12
<b>Hitachi</b>	NT50AE2, N50GS	NT50AE2, N50GS	NT50AE2, N50GS	NT50AE2, N50GS	NT50AE2, N50GS
<b>JK/Kihlberg</b>	JK 24-512	JK 24-512	JK 24-512	JK 24-512	JK 24-512
<b>Makita</b>	AF505	AF505	AF505	AF505	AF505
<b>Max</b>	NF 210-16- 25, NF 201/18-35, NF235/18, NF221/18-55, NF255/ST/18, NF2555-ST	NF 210-16- 25, NF 201/18-35, NF235/18, NF221/18-55, NF255/ST/18, NF2555-ST	NF 210-16- 25, NF221/18- 55,NF255- ST/18, NF2555F- ST	NF 210-16- 25	NF 210-16- 25
<b>Mec Tools</b>	071-018	071-018	071-018	071-018	071-018
<b>Paslode</b>	FN1850, IM50F18	FN1850, IM50F18	FN1850, IM50F18	FN1850, IM50F18	FN1850, IM50F18
<b>Rapid</b>	EN50	EN50	EN50	EN50	EN50
<b>Senco</b>	LNS 156e, LN 3215e, LNS 3215e, HNS 3215e, LNS156p, HNS 156p, LNS 3215p, HNS 3215p, LNS 5015p, HNS 5015p	LNS 156e, LN 3215e, LNS 3215e, HNS 3215e, LNS156p, HNS 156p, LNS 3215p, HNS 3215p, LNS 5015p, HNS 5015p	LNS 156e, LN 3215e, LNS 3215e, HNS 3215e, LNS156p, HNS 156p, LNS 3215p, HNS 3215p, LNS 5015p, HNS 5015p	LNS 156e, LN 3215e, LNS 3215e, HNS 3215e, LNS156p, HNS 156p, LNS 3215p, HNS 3215p, LNS 5015p, HNS 5015p	LNS 156e, LN 3215e, LNS 3215e, HNS 3215e, LNS156p, HNS 156p, LNS 3215p, HNS 3215p, LNS 5015p, HNS 5015p
<b>Swedol</b>	VT-4572	VT-4572	VT-4572	VT-4572	VT-4572
<b>Tjep</b>	F-18/45, F18/50, TF- 18/40, TF- 18/50, D18/50, 90/F18	F-18/45, F18/50, TF- 18/40, TF- 18/50, D18/50, 90/F18	F-18/45, F18/50, TF- 18/40, TF- 18/50, D18/50, 90/F18	F-18/45, F18/50, TF- 18/40, TF- 18/50, D18/50, 90/F18	F-18/45, F18/50, TF- 18/40, TF- 18/50, D18/50, 90/F18
<b>Workman</b>	MB18	MB18	MB18	MB18	MB18

no: <http://no.fast-fastening.com/fast/lboxServlet?p=IXK090&AID=294053>